

Coin Changer Acceptor Installation Overview

Coinco 3000 – 9000 / Mars TRC 60x0 & 6800

Turn power to machine off when installing acceptor

COINCO

The acceptors for Coinco 3000 and 9000 (9300L, 9302L, 9340S, 9360s, 9370S) changers do not require tuning when installed in a working changer body. There are 3 versions of 9000 acceptors so be sure the connector at the end of the ribbon cable on the replacement unit is the same as the acceptor you are replacing.

In the event the coin changer does not accept coins please see video titled – “Coin changer troubleshooting - determine if host vending machine enable circuit is working”

Mars / MEI

When an acceptor is installed in a Mars TRC 6000/6010 and TRC6800/TRC6800H it needs to be tuned about 30% of the time.

In the event one or more coin values are not accepted, tuning will be required.

If you have Mars Coin changer model TRC6000 or TRC 6010 see video titled – Tuning a TRC 6000

If you have Mars Coin changer model TRC6800 see video titled – Tuning a Mars TRC6800H

If after tuning no coins are accepted see the video titled “Coin changer troubleshooting - determine if host vending machine enable circuit is working”

HELPFUL YOUTUBE VIDEOS

Coin changer troubleshooting - determine if host vending machine enable circuit is working:

<https://youtu.be/-B30c7i6G3M>

Tuning a TRC 6000:

<https://youtu.be/DjRh1AH35rc>

Tuning a Mars TRC6800H:

<https://youtu.be/8YbmZR1F2Ok>

If you need additional help:

Contact the distributor that sold you the machine

Visit helpwithvending.com